



ISO 9001-2008 Certified

Audio/Video Equipment Repair List

Greenbrier Technical Services Inc.
PO Drawer 588 - Lewisburg, WV 24901
869 Edgar Avenue - Ronceverte, WV 24970
Phone: 304-645-6263 / Fax 304-645-4515
info@greenbrier-tech.com

Revision T – 8/25/2017



Audio / Video Repair Price List
 869 Edgar Avenue
 Ronceverte, WV 24970
 304-645-6263
 Revision T - 8/25/2017

American Vault	OEM P/N	GTS P/N	Repair Price
Audio System	5901	950-700000	\$234.00
ICE-8 Teller Console	5801	950-700001	\$200.00
ICE-4 Matrix	5402	950-700002	\$265.00
ICE-4 Teller Console	5401	950-700003	\$267.00
ICE-2 Matrix	5202	950-700004	\$114.00
ICE-2 Teller Console	5201	950-700005	\$300.00
ICE-1 Matrix	5102	950-700006	\$100.00
ICE-1 Teller Console	5101	950-700007	\$200.00

Audio Authority	OEM P/N	GTS P/N	Repair Price
Audio Counter Station w/ Cable	1500	950-700008	\$280.00
Compact Teller Console with Headset	1500AH	950-700124	\$283.00
Video Add-On (Dispenser for 1500) w/ Cable	1501	950-700061	\$435.00
2-Way Video Add-On for Counter Station(1500)	1502	950-700009	\$634.00
2 Way Video Add on for the 1500A	1502A	950-700097	\$580.00
Audio Hub (2 on 4 Application)	1509	950-700011	\$100.00
Audio/Video Intercom Hub (4 Teller/4 Lanes)	1510	950-700012	\$532.00
Audio/Video Intercom Hub (4 Teller/8 Lanes)	1511	950-700062	\$667.00
Audio/Video Intercom Hub (4 Teller/12 Lanes)	1512	950-700013	\$800.00
Audio/Video Intercom Hub (8 Teller/16 Lanes)	1513	950-700014	\$800.00
4 Port Counter Station Expansion Card	1515	950-700015	\$100.00
4 Port Customer Station Expansion Card	1516	950-700016	\$100.00
System Card - SD/SDHC Capable	1517SD	950-700103	\$140.00
Audio/Video Lane Station	1520	950-700060	\$97.00
Complete Customer Audio/Video Station	1522	950-700017	\$800.00
Video Add-On (Drive Up Units)	1523	950-700018	\$640.00
Video Add-On (Drive Up Units)	1524	950-700019	\$667.00
Arm Handset Kit for 1520	1540	950-700021	\$169.00
Digital Wireless Headset Kit for 15xx	1542	950-700023	\$176.00
Wired Headset Kit for 1500	1543	950-700024	\$100.00
Handset Kit for 1500 (6')	1544	950-700025	\$100.00
IR Traffic Sensor Kit (Drive Up Units)	1547	950-700026	\$155.00
4x1 Headset Selector	1548	950-700027	\$100.00
CCA Countertop Console	1561	950-700122	\$241.00
Camera Tilt Mechanism, Customer Station (Long Version)	804-039	950-700087	\$180.00
Camera Tilt Mechanism, Customer Station (Short Version)	804-057	950-700118	\$180.00
Pixam Camera with Tilt Mechanism, Customer Station	804-039P	950-700123	\$230.00
Repair, Audio Authority, 1-16 Lane teller console W/2 way video	1500-1502	950-700133	\$922.00
Audio Counter Station w/ Cable	1500A	950-700095	\$280.00

Greyfield	OEM P/N	GTS P/N	Repair Price
Teller Console, Single Lane	3001-1	950-700069	\$310.00
12 Lane Audio Console	3001-12	950-700078	\$200.00
8 Lane Teller Console w/ Video	4101-8	950-700125	\$700.00
Audio Matrix (3 Teller/4 Lanes)	4002-4	950-700063	\$233.00
Audio Matrix (6 Teller/12 Lanes)	4002-12	950-700121	\$265.00
Bi-Directional Video Matrix	4005-4	950-700065	\$230.00
Mini Audio Matrix (2 Teller)	5004	950-700032	\$128.00
Mini Audio/Video Matrix (2 Teller)	5006	950-700033	\$367.00
Wireless Adapter	5014	950-700034	\$100.00
Wireless Teller System (5014-5016)	5015	950-700035	\$235.00
2 Lane Wireless Audio Console	G5030-2	950-700036	\$200.00
4 Lane Wireless Audio Console	G5030-4	950-700037	\$202.00
8 Lane Wireless Audio Console	G5030-8	950-700038	\$270.00
Wireless Lane Module	G5031-LM	950-700040	\$195.00
Teller Audio Console, 6 Lane	5001-6	950-700088	\$157.00
Teller Audio Console, 2 Lane	3001-2	950-700093	\$140.00
Teller Audio Console, 6 Lane	3001-6	950-700089	\$174.00
Matrix (4 Lane)	3002-4	950-700094	\$141.00
Audio Matrix (2 Lanes)	3004-2	950-700092	\$169.00
2 Lane Teller Console w/ Cable	3301-2	950-700100	\$140.00
6 Lane Teller Console w/ Cable	3301-6	950-700101	\$174.00
12 Lane Teller Console w/Cable	3301-12	950-700102	\$194.00
Teller Audio Console, Stand Alone	4001-1	950-700104	\$140.00
Teller Audio Console	4001-6	950-700067	\$176.00
Teller Console, 2 Lane	4001-2	950-700074	\$140.00
Audio Matrix (8 Lanes / 6 Tellers)	4002-8	950-700106	\$230.00
Audio Matrix (2 Lanes)	4004-2	950-700120	\$181.00
2 Lane Teller Console	5001-1	950-700098	\$265.00
2 Lane Teller Console	5001-2	950-700070	\$280.00
12 Lane Teller Console	5001-12	950-700129	\$295.00
LCD Teller Video w/Camera	G5450	950-700041	\$471.00
1 or 2 Lane Intercom System	G5501-1	950-700042	\$200.00
12 Lane Teller Console w/Cable	G5501-12	950-700043	\$158.00
2 Lane Teller Console w/Cable	G5501-2	950-700066	\$140.00
4 Lane Teller Console w/Cable	G5501-4	950-700044	\$180.00

Greyfield	OEM P/N	GTS P/N	Repair Price
8 Lane Teller Console w/Cable	G5501-8	950-700045	\$197.00
Customer 10" Monitor	G5517	950-700046	\$395.00
Customer 10" Monitor (Sun View)	G5517-SUN	950-700047	\$395.00
Base, Stand Monitor with Camera	G5550	950-700048	\$565.00
Base, Stand Monitor without Camera	G5550-1	950-700049	\$200.00
Audio Matrix (6 Teller/12 Lanes)	5002-12	950-700050	\$370.00
Audio Matrix (3 Teller/4 Lanes)	5002-4	950-700064	\$200.00
Audio Matrix (6 Teller/8 Lanes)	5002-8	950-700051	\$260.00
Bi-Directional Video Matrix	5005-12	950-700052	\$438.00
Bi-Directional Video Matrix (5002-4)	5005-4	950-700053	\$260.00
Bi-Directional Video Matrix (5002-8)	5005-8	950-700054	\$395.00
Audio Matrix (1 Teller / 2 Lanes)	5003-2	950-700099	\$185.00

Diebold	OEM P/N	GTS P/N	Repair Price
2-Way, CCTV, Teller Unit, Refurbishment	00013523000A	950-700091	\$1,725.00
Teller Console, Autogain 3/6	11036497000A	950-700068	\$570.00
Matrix (2 Lanes / 2 Tellers)	MSN79441000A	950-700071	\$217.00
Matrix (4 Lanes / 3 Tellers)	MSN79442000A	950-700072	\$269.00
Matrix (8 Lanes / 6 Tellers)	MSN79443000A	950-700073	\$289.00
Teller Console, 6 Lane	N67444	950-700075	\$316.00
Teller Console, 2 on 5	D7599933	950-700076	\$276.00
Teller Audio Box, Comm Master	41015082000A	950-700079	\$260.00
Teller Audio Box, Comm Master	41015082000B	950-700080	\$263.00
CCA, Audio Switcher	41017127000A	950-700081	\$320.00
Teller Console, 8x16	00013541000A	950-700082	\$334.00
8x16 Customer Interface PCB	41017131000A	950-700083	\$168.00
Speaker PCB	39009603000E	950-700084	\$100.00
Amp Tac Head PCB	41016701000A	950-700085	\$100.00
Teller Audio Console, Single Lane	00013544000A	950-700090	\$254.00
Main Audio Switcher PCB, 2x4 Commaster	49010070000A	950-700108	\$269.00
8x16 Matrix Switcher, Video	41017399000A	950-700109	\$600.00
4x4 Matrix Switcher, Video	00013653000A	950-700128	\$265.00
4x8 Matrix Switcher, Video	00013653000B	950-700127	\$302.00
Countertop Sound Model Single Station, Autogain (Lefebure)	62-0726-4	950-700137	\$402.00
8x16 Teller Unit Membrane Overlay (New Unit - Not a repair)		936-011088	\$145.00

Bavis	OEM P/N	GTS P/N	Repair Price
Audio PCB	22118011	950-700086	\$114.00
Comco			
	OEM P/N	GTS P/N	Repair Price
AVA 5304 Audio Console, 4 Lane	100039	950-700028	\$263.00
AVA 5302 Audio Console, 2 Lane	100040	950-700029	\$250.00
Assembly, Matrix, Audio, SM44, AVA 5300 Series	200822	950-700030	\$235.00
Audio/Video Console	TVM1000GD	950-700031	\$707.00
Audio/Video Console, 1-16 Lanes, 2 way Video	TVM1000VM	950-700136	\$471.00
AVA 530X Audio Console, 2 Lane, Stand Alone	AVA 503X	950-700105	\$195.00
Assembly, Matrix, Audio, SM-2, AVA 5300 Series	SM-2	950-700117	\$256.00
SSE			
	OEM P/N	GTS P/N	Repair Price
Four Lane Audio Console	SK7500134	950-700055	\$503.00
Interconnect 4 Channel	SK75-0021	950-700056	\$270.00
2 Channel Interconnect PCB, 2/4 Matrix	SK75-0022	950-700115	\$281.00
2 Channel Audio Console Assembly	SK75-0097-2	950-700057	\$503.00
Video Switcher Assembly	SK750188	950-700058	\$683.00
Two Channel Interconnect Board	CB0082	950-700059	\$101.00
Repairs do not include microphones and cables, unless stated. Microphones can be purchased for an additional charge.			