

American Vault	OEM P/N	GTS P/N	Repair Price
Audio System	5802	950-700000	\$263.00
ICE-8 Teller Console	5801 or 5800	950-700001	\$224.00
ICE-4 Matrix	5402	950-700002	\$297.00
ICE-4 Teller Console	5401	950-700003	\$300.00
ICE-2 Matrix	5202	950-700004	\$128.00
ICE-2 Teller Console	5201	950-700005	\$336.00
ICE-1 Matrix	5102	950-700006	\$112.00
ICE-1 Teller Console	5101	950-700007	\$224.00

Audio Authority	OEM P/N	GTS P/N	Repair Price
Audio Counter Station w/ Cable	1500	950-700008	\$314.00
Compact Teller Console with Headset	1500AH	950-700124	\$317.00
Video Add-On (Dispenser for 1500) w/ Cable	1501	950-700061	\$488.00
2-Way Video Add-On for Counter Station(1500)	1502	950-700009	\$711.00
2 Way Video Add on for the 1500A	1502A	950-700097	\$650.00
Audio Hub (2 on 4 Application)	1509	950-700011	\$112.00
Audio/Video Intercom Hub (4 Teller/4 Lanes)	1510	950-700012	\$596.00
Audio/Video Intercom Hub (4 Teller/8 Lanes)	1511	950-700062	\$748.00
Audio/Video Intercom Hub (4 Teller/12 Lanes)	1512	950-700013	\$896.00
Audio/Video Intercom Hub (8 Teller/16 Lanes)	1513	950-700014	\$896.00
4 Port Counter Station Expansion Card	1515	950-700015	\$112.00
4 Port Customer Station Expansion Card	1516	950-700016	\$112.00
System Card - SD/SDHC Capable	1517SD or 1517	950-700103	\$157.00
Audio/Video Lane Station	1520	950-700060	\$109.00
Complete Customer Audio/Video Station	1522	950-700017	\$896.00
Video Add-On (Drive Up Units)	1523	950-700018	\$717.00
Video Add-On (Drive Up Units)	1524	950-700019	\$748.00
Arm Handset Kit for 1520	1540	950-700021	\$190.00
Digital Wireless Headset Kit for 15xx	1542	950-700023	\$198.00
Wired Headset Kit for 1500	1543	950-700024	\$112.00
Handset Kit for 1500 (6')	1544	950-700025	\$112.00
IR Traffic Sensor Kit (Drive Up Units)	1547	950-700026	\$174.00
4x1 Headset Selector	1548	950-700027	\$112.00
CCA Countertop Console	1561	950-700122	\$270.00
Camera Tilt Mechanism, Customer Station (Long Version)	804-039	950-700087	\$202.00
Camera Tilt Mechanism, Customer Station (Short Version)	804-057	950-700118	\$202.00
Pixam Camera with Tilt Mechanism, Customer Station	804-039P	950-700123	\$258.00
1 Way Video Add on for the 1500A	1501A	950-700096	\$446.00
Repair, Audio Authority, 1-16 Lane teller console W/2 way video	1500-1502	950-700133	\$1033.00
2 Way Video Add-On, LED	1502L	950-700131	\$711.00
Intercom Hub, 8 X 8	1530	950-700130	\$722.00
Audio Counter Station w/ Cable	1500A	950-700095	\$314.00

Greyfield	OEM P/N	GTS P/N	Repair Price
Teller Console, Single Lane	3001-1	950-700069	\$648.00
12 Lane Audio Console	3001-12	950-700078	\$224.00
8 Lane Teller Console w/ Video	4101-8	950-700125	\$784.00
Audio Matrix (3 Teller/4 Lanes)	4002-4	950-700063	\$261.00
Audio Matrix (6 Teller/12 Lanes)	4002-12	950-700121	\$297.00
Bi-Directional Video Matrix	4005-4	950-700065	\$258.00
Mini Audio Matrix (2 Teller)	5004	950-700032	\$144.00
Mini Audio/Video Matrix (2 Teller)	5006	950-700033	\$412.00
Wireless Adapter	5014	950-700034	\$112.00
Wireless Teller System (5014-5016)	5015	950-700035	\$264.00
2 Lane Wireless Audio Console	G5030-2	950-700036	\$224.00
4 Lane Wireless Audio Console	G5030-4	950-700037	\$227.00
8 Lane Wireless Audio Console	G5030-8	950-700038	\$303.00
Wireless Lane Module	G5031-LM	950-700040	\$219.00
Teller Audio Console, 6 Lane	5001-6	950-700088	\$176.00
Teller Audio Console, 2 Lane	3001-2	950-700093	\$157.00
Teller Audio Console, 6 Lane	3001-6	950-700089	\$195.00
Matrix (4 Lane)	3002-4	950-700094	\$158.00
Audio Matrix (2 Lanes)	3004-2	950-700092	\$190.00
2 Lane Teller Console w/ Cable	3301-2	950-700100	\$157.00
6 Lane Teller Console w/ Cable	3301-6	950-700101	\$195.00
12 Lane Teller Console w/Cable	3301-12	950-700102	\$218.00
Teller Audio Console, Stand Alone	4001-1	950-700104	\$157.00
Teller Audio Console	4001-6	950-700067	\$198.00
Teller Console, 2 Lane	4001-2	950-700074	\$157.00
Audio Matrix (8 Lanes / 6 Tellers)	4002-8	950-700106	\$258.00
Audio Matrix (2 Lanes)	4004-2	950-700120	\$203.00
2 Lane Teller Console	5001-1	950-700098	\$297.00
2 Lane Teller Console	5001-2	950-700070	\$314.00
12 Lane Teller Console	5001-12	950-700129	\$331.00
LCD Teller Video w/Camera	G5450	950-700041	\$528.00
1 or 2 Lane Intercom System	G5501-1	950-700042	\$224.00
12 Lane Teller Console w/Cable	G5501-12	950-700043	\$177.00
2 Lane Teller Console w/Cable	G5501-2	950-700066	\$157.00
4 Lane Teller Console w/Cable	G5501-4	950-700044	\$202.00

Greyfield	OEM P/N	GTS P/N	Repair Price
8 Lane Teller Console w/Cable	G5501-8	950-700045	\$210.00
Customer 10" Monitor	G5517	950-700046	\$443.00
Customer 10" Monitor (Sun View)	G5517-SUN	950-700047	\$443.00
Base, Stand Monitor with Camera	G5550	950-700048	\$633.00
Base, Stand Monitor without Camera	G5550-1	950-700049	\$224.00
Audio Matrix (6 Teller/12 Lanes)	5002-12	950-700050	\$415.00
Audio Matrix (3 Teller/4 Lanes)	5002-4	950-700064	\$247.00
Audio Matrix (6 Teller/8 Lanes)	5002-8	950-700051	\$292.00
Bi-Directional Video Matrix	5005-12	950-700052	\$491.00
Bi-Directional Video Matrix (5002-4)	5005-4	950-700053	\$292.00
Bi-Directional Video Matrix (5002-8)	5005-8	950-700054	\$443.00
Hamilton/Greyfield Audio/Video Mini Matrix, Model 4006	4006	950-700139	\$409.00
Audio Matrix (1 Teller / 2 Lanes)	5003-2 or 5003	950-700099	\$208.00

Diebold	OEM P/N	GTS P/N	Repair Price
2-Way, CCTV, Teller Unit, Refurbishment	00013523000A	950-700091	\$1,932.00
Teller Console, Autogain 3/6	11036497000A	950-700068	\$639.00
Matrix (2 Lanes / 2 Tellers)	MSN79441000A	950-700071	\$244.00
Matrix (4 Lanes / 3 Tellers)	MSN79442000A	950-700072	\$302.00
Matrix (8 Lanes / 6 Tellers)	MSN79443000A	950-700073	\$324.00
Teller Console, 6 Lane	N67444	950-700075	\$354.00
Teller Console, 2 on 5	D7599933	950-700076	\$310.00
Teller Audio Box, Comm Master	41015082000A	950-700079	\$292.00
Teller Audio Box, Comm Master	41015082000B	950-700080	\$295.00
CCA, Audio Switcher	41017127000A	950-700081	\$359.00
Teller Console, 8x16	00013541000A	950-700082	\$375.00
8x16 Customer Interface PCB	41017131000A	950-700083	\$189.00
Speaker PCB	39009603000E	950-700084	\$112.00
Amp Tac Head PCB	41016701000A	950-700085	\$112.00
Teller Audio Console, Single Lane	00013544000A	950-700090	\$285.00
Main Audio Switcher PCB, 2x4 Commaster	49010070000A	950-700108	\$302.00
8x16 Matrix Switcher, Video	41017399000A	950-700109	\$672.00
4x4 Matrix Switcher, Video	00013653000A	950-700128	\$297.00
4x8 Matrix Switcher, Video	00013653000B	950-700127	\$339.00
Countertop Sound Model Single Station, Autogain (Lefebure)	62-0726-4	950-700137	\$451.00
Diebold 816 Video Switcher, 4 Teller, 8 Customer	41017399000B	950-700140	\$336.00
Audio Matrix, Diebold 816 series, 4 teller, 4 customer	41017127000C	950-700142	\$308.00
CCA, AUD SWTCR, COMMASTER, Top Assy, 2 LN 4 TLR Inc	41015367000A	950-700119	\$297.00
8x16 Teller Unit Membrane Overlay (New Unit - Not a repair)	31020145000A WITHOUT PCB	936-011088	\$163.00

Bavis	OEM P/N	GTS P/N	Repair Price
Audio PCB	22118011	950-700086	\$128.00
Comco			
	OEM P/N	GTS P/N	Repair Price
AVA 5304 Audio Console, 4 Lane	100039/AVA-5304	950-700028	\$295.00
AVA 5302 Audio Console, 2 Lane	100040/AVA-5302	950-700029	\$280.00
Assembly, Matrix, Audio, SM44, AVA 5300 Series	200822	950-700030	\$264.00
Audio/Video Console	TVM1000GD	950-700031	\$792.00
Audio/Video Console, 1-16 Lanes, 2 way Video	TVM1000VM	950-700136	\$528.00
AVA 530X Audio Console, 2 Lane, Stand Alone	AVA 503X	950-700105	\$219.00
Assembly, Matrix, Audio, SM-2, AVA 5300 Series	SM-2	950-700117	\$287.00
SSE			
	OEM P/N	GTS P/N	Repair Price
Four Lane Audio Console	SK7500134	950-700055	\$564.00
Interconnect 4 Channel	SK75-0021	950-700056	\$303.00
2 Channel Interconnect PCB, 2/4 Matrix	SK75-0022	950-700115	\$315.00
2 Channel Audio Console Assembly	SK75-0097-2	950-700057	\$564.00
Video Switcher Assembly	SK750188	950-700058	\$765.00
Two Channel Interconnect Board	CB0082	950-700059	\$114.00
Repairs do not include microphones and cables, unless stated. Microphones can be purchased for an additional charge.			